



PERKHIDMATAN MEMBAIKPULIH KEROSAKAN 'SPI BOARD V8' BAGI ALATAN 'SCANNING PROBE MICROSCOPE' DI PUSAT PENGAJIAN KEJURUTERAAN BAHAN & SUMBER MINERAL,  
UNIVERSITI SAINS MALAYSIA, KAMPUS KEJURUTERAAN, NIBONG TEBAL, PULAU PINANG

TECHNICAL SPECIFICATION SCHEDULE

Quotation No. : SH2/22/ENT/PBAHAN/P/00032

ITEM NO.	UNIVERSITY’S DESCRIPTION	QUANTITY	BIDDER’S SPECIFICATION (Please Write Your Specification In This Column)	TECHNICAL EVALUATION (For Official Use Only)
1	<p><b>A. ITEM</b> Scanning Probe Microscope Seiko SPI3800</p> <p><b>B. DESCRIPTION</b> Replace SPI Board V8 on Scanning Probe Microscope Seiko SPI3800</p> <p><b>C. ESSENTIAL FEATURES</b></p> <ul style="list-style-type: none"><li>Only qualified or Seiko authorized supplier are invited to submit the quotation.</li><li>Must provide an Seiko confirmation letter.</li></ul> <p><b>D. TECHNICAL SPECIFICATION</b></p> <ul style="list-style-type: none"><li>To replace the SPI Board V8 with a new one.</li><li>To install and commission at the School of Materials and Mineral Resources Engineering.</li><li>To check the performance of Scanning Probe Microscope Seiko SPI3800 to ensure that is fully functional after installation.</li></ul> <p><b>E. STANDARD REQUIREMENTS AND INSTRUCTIONS</b></p> <p>a. The job must be warranted against installation and manufacturing defects for at least 12 months from the date of commissioning.</p> <p>b. The supplier has to give information regarding their servicing capabilities / after sales service for the equipment quoted.</p> <p>NOTE: FOR ALL SUPPLIES, PLEASE OFFER THE MINIMUM REQUIRED SPECIFICATIONS OR BETTER VERSIONS.</p>	1 unit		

.....  
(Signature and Chop of Contractor)